



CONTAP-195972：系统级硬件诊断报告 X4032S543015TNVF 和 X4030S543030TNVF 驱动器的信息不正确

<https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-Issues/CONTAP-195972>

Updated: Wed, 22 Apr 2026 08:25:12 GMT

问题描述

系统级硬件诊断报告来自 X4032S543015TNVF 和 X4030S543030TNVF 驱动器的"扫描系统"操作的驱动器信息不正确：部件号、序列号和固件版本。

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information