



ONTAP-320179 : 磁盘类型X357_SLBPE3T8ATE固件NA51出现高故障率

<https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-Issues/CONTAP-320179>

Updated: Wed, 22 Apr 2026 10:05:14 GMT

问题描述

- 磁盘驱动器断开连接

```
pmcsas_admin_0: sas.adapter.debug:info]: params: {'adapterName': '0a',  
'debug_string': 'BAD destination on OPEN (0x14) -- delaying: dev 0b.00.22, cdb  
0x28:d98cc920:0008 (0/90181), NDU 0x0'}
```

- 系统尝试恢复驱动器

```
scsi_cmdblck_strthr_admin: disk.timeout.flush.start:debug]: Aggressive timeout flush  
started on disk 0a.00.22.
```

- 磁盘驱动器最终丢失

```
svc_queue_thread: cf.disk.inventory.mismatch:error]: Status of the disk ??  
(6000C500:EC999027:500A0981:00000001:00000000:00000000:00000000:00000000:00000000:00000000)  
has recently changed or the node (node-01) is missing the disk.
```