



CONTAP-333935 : BMC 17.3 包括 FAS2820 系统的增强功能

<https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-Issues/CONTAP-333935>

Updated: Wed, 22 Apr 2026 07:31:35 GMT

问题描述

适用于 NetApp FAS2820 系统的基板管理控制器 (BMC) 17.3 包含以下错误修复和增强功能，可提高可靠性和安全性：

- 将 OpenSSL 更新到 3.0.14
- 将 OpenSSH 更新到 9.8p1
- 支持可配置的 SSH 公钥和主机密钥算法
- ONTAP 横幅支持 BMC 登录
- 错误 1603286 - 当 BMC 仅配置 IPv6 地址时，ONTAP 与合作伙伴 BMC 的通信可能无法正常工作
- 错误 CFBMC-3955 - BMC 固件升级后温度不足警告
- 错误 CFBMC-4623 - BMC CLI 的 BMC 更新可能会被密码提示中断
- 错误 CFBMC-4812 - BMC 固件可以使用 .zip 固件文件从 BMC CLI 更新

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information