



CONTAP-336549 : 新 SCBPE* NA01 驱动器固件中的可靠性改进

<https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-Issues/CONTAP-336549>

Updated: Wed, 22 Apr 2026 07:30:39 GMT

问题描述

SCBPE* NA01 固件维护版本包含以下改进：

- 改进以减少驱动器断言（内部重新启动）的可能性
- 改进以避免可能的超时和无响应
- 一般维护版本以使驱动器与最新的可靠性改进保持同步

部件号 型号 容量 新固件

X318A-R6 X318_SCBPE08TA07 8.0TB NA01
X336A-R6 X336_SCBPE04TA07 4.0TB NA01
X375A X375_SCBPE04TA07 4.0TB NA01
X376A X376_SCBPE08TA07 8.10TB NA01
X377A X377_SCBPE10TA07 10.0TB NA01
X380A X380_SCBPE10TA07 10.0TB NA01
X477A-R6 X477_SCBPE04TA07 4.0TB NA01

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information