



CONTAP-411595: 硬件诊断"四端口 25GbE 以太网 ConnectX-7 VPI: 失败"

<https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-Issues/CONTAP-411595>

Updated: Wed, 22 Apr 2026 13:04:14 GMT

问题描述

X60132A : 4端口，10G/25G 以太网控制器 CX7

四端口 25GbE NIC 因系统级硬件诊断显示为 FAILED
仅在 DIAG 测试期间报告错误。ONTAP 启动后，端口显示为 UP。

系统测试摘要：

双端口 100GbE 以太网 ConnectX-6 DX : FAILED

四端口 25GbE 以太网 ConnectX-7 VPI : FAILED ★

扫描系统

=====

OCP 四端口 25GbE 以太网 ConnectX-7 VPI :

接口 链路速率 固件版本

e3a Down Unknown! 28.41.1000 (NAP0000000029)

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

e3b Down Unknown! 28.41.1000 (NAP0000000029)
e3c Down Unknown! 28.41.1000 (NAP0000000029)
e3d Down Unknown! 28.41.1000 (NAP0000000029)

=====

四端口 25GbE 以太网 ConnectX-7 VPI 外部回环测试失败 ★