



CONAP-463367 : BMC 10.10P1 包括AFF A800、AFF C800、ASA A800 和ASA C800系统的增强功能

<https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-Issues/CONTAP-463367>

Updated: Wed, 22 Apr 2026 07:32:29 GMT

问题描述

NetApp AFF A800、AFF C800、ASA A800 和 ASA C800 系统的底板管理控制器 (BMC) 10.10P1 包含错误修复和增强功能，提高了可靠性和安全性。

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information