



---

## CONTAP-82619 : Broadcom 交换机频繁触发 "SwitchTemperatureCritical\_Alert"

<https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-Issues/CONTAP-82619>

Updated: Wed, 22 Apr 2026 09:00:24 GMT

### 问题描述

- 当交换机端的默认交换机温度阈值设置为 45 摄氏度时，频繁触发 "SwitchTemperatureCritical\_Alert"
- 在这种情况下，"system cluster-switch temperature show" 输出中的 "status" 字段也将更改为 "Critical"