



CONAP-383633 : 新发售的AFF 2020系统无法在集群设置期间自动创建集群LID

https://kb-cn-stage.netapp.com/on-prem/ontap/Ontap_OS/OS-Issues/CONTAP-383633

Updated: Wed, 22 Apr 2026 08:34:59 GMT

问题描述

- 在集群设置期间、此过程将失败：

```
Do you want to create a new cluster or join an existing cluster? {create/join}:  
create
```

```
Error: command failed: Creation of auto-cluster LIFs is not complete. Verify  
that this node is cabled correctly, and then try the operation again.
```

- 缺少集群端口(e4a、e4b或e2a、e4a、具体取决于系统配置)：

```
::> network port show  
Port      IPspace      Broadcast Domain Link MTU   Admin/Oper  Status  
-----  
e0M       Default      Default      up   1500   auto/1000   healthy  
e4c       Default      Default      down 1500   auto/--  
e4d       Default      Default      down 1500   auto/--
```

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information