



# NiCE

---

## CONTAP-488221 : 部分磁盘在 FAS9500 上显示 config.sameHA 错误

[https://kb-cn-stage.netapp.com/on-prem/ontap/Ontap\\_OS/RAID\\_Issues/CONTAP-488221](https://kb-cn-stage.netapp.com/on-prem/ontap/Ontap_OS/RAID_Issues/CONTAP-488221)

Updated: Thu, 04 Jun 2026 01:17:02 GMT

### 问题描述

在升级过程中，观察到以下 **config.sameHA** 错误：

ONTAP:9.16.1P14

EMS 日志：

```
[config.sameHA:error]: Disk 2.2.9 and other disks attached to the same port are dual-attached to the same adapter. For improved availability you should dual-attach them to separate adapters.
```

```
[config_check: config.sameHA:error]: Disk 2.3.30 and other disks attached to the same port are dual-attached to the same adapter. For improved availability you should dual-attach them to separate adapters.
```

```
[config_check: config.sameHA:error]: Disk 3.11.22 and other disks attached to the same port are dual-attached to the same adapter. For improved availability you should dual-attach them to separate adapters.
```

```
[config_check: config.sameHA:error]: Disk 3.12.4 and other disks attached to the same port are dual-attached to the same adapter. For improved availability you should dual-attach them to separate adapters.
```

---

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

系统存储配置：四路 HA