



CXone Mpower EXPERT

某些HBA上的吞吐量较低

https://kb-cn-stage.netapp.com/on-prem/ontap/Perf/Perf-KBs/Lower_throughput_on_certain_HBA

Updated: Wed, 22 Apr 2026 07:33:09 GMT

适用场景

- ONTAP 9
- FCP

问题描述

- 新的超级计算机无法实现与其小型前代产品相同的吞吐量。
- 吞吐量为1.4 GB/秒、而不是4.0 GB/秒
- 在NetApp上未发现延迟。

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information