



disk.encryptCmdFailed 磁盘加密失败

https://kb-cn-stage.netapp.com/on-prem/ontap/dm/Encryption/Encryption-KBs/disk.encryptCmdFailed_...

Updated: Wed, 22 Apr 2026 03:31:33 GMT

适用场景

采用外部密钥管理器(EKM)和NetApp存储加密(NSE)的ONTAP 9

问题描述

- 正在尝试向现有 NSE 集群添加磁盘

```
NSECluster::> encryption disk modify -disk 0.10.0 -data-key-id  
000000000000000000002000000000012345AB1C2D123E1F1234GH1IJ123LMN
```

- 导致此错误

Time	Node	Severity	Event
9/27/2021 12:56:20	NSECluster-01	ERROR	disk.encryptCmdFailed: Encrypting disk 0a.10.0 failed disk encrypt modify command with error status Authentication key

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

not found. (0xe).