



---

## ONTAP EMS报告netinet.Ethr.arpstorm

[https://kb-cn-stage.netapp.com/on-prem/ontap/dm/FlexGroup/FlexGroup-KBs/ONTAP\\_EMS\\_reports\\_n...](https://kb-cn-stage.netapp.com/on-prem/ontap/dm/FlexGroup/FlexGroup-KBs/ONTAP_EMS_reports_n...)

Updated: Fri, 24 Apr 2026 10:20:54 GMT

### 适用场景

ONTAP 9

### 问题描述

EMS仅记录了以下错误一次：

```
netinet.rthr.arpstorm: The node detected a possible ARP storm on port e0M.  
Detected rate: 5001 packets per second.
```