



# CXone Mpower EXPERT

---

## 无法识别已添加的磁带机

[https://kb-cn-stage.netapp.com/on-prem/ontap/dp/NDMP/NDMP-KBs/Added\\_tape\\_drive\\_can\\_not\\_be\\_s...](https://kb-cn-stage.netapp.com/on-prem/ontap/dp/NDMP/NDMP-KBs/Added_tape_drive_can_not_be_s...)

Updated: Wed, 22 Apr 2026 17:28:36 GMT

### 适用场景

- ONTAP 9
- 不同供应商的磁带库

### 问题描述

- 将光纤通道连接的磁带库添加到节点后、磁带驱动器不可用
- 连接的节点看不到中的磁带 [Storage Tape Show](#)
- [storage\\_path show](#) 显示了磁带的路径