



COINTA-58732：系统在正常运行994天后意外重新启动、并显示"整型除法故障"

<https://kb-cn-stage.netapp.com/on-prem/ontap/da/SAN/SAN-Issues/CONTAP-58732>

Updated: Wed, 22 Apr 2026 07:31:19 GMT

问题描述

ONTAP节点意外重新启动、并显示消息：

整数除法故障：num 18 code 0 cs：rip 0x20：0xfffff9a995842 rflags 0x10246 in SK Process callout on Release 9.4P3
(C)