



磁盘更换磁盘保持未分配状态后，必须手动分配

https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/After_disk_replacement_disk_remain...

Updated: Wed, 22 Apr 2026 10:27:38 GMT

适用场景

- ONTAP 9
- DS460

问题描述

- 更换故障磁盘后、未自动分配替代磁盘
- 需要手动分配