



闪存卡上的琥珀色LED亮起、但未出现硬件故障

https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/Amber_LED_lit_on_flash_cache_card...

Updated: Wed, 22 Apr 2026 08:25:06 GMT

适用场景

- 全FAS平台
- 全AFF平台

问题描述

- 闪存卡状态正常

```
slot 6-1: Flash Cache NVMe
  Serial Number:    47XXXXXXXXXMU
  Part Number:     119-00207
  Hardware Revision:  A1
  Firmware Version:  NA05
  Firmware File:    X9170_0000Z6300NVM
  Model Name:      X9170A
```

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

Capacity: 1024 GB

State: ok

- 卡上的琥珀色指示灯亮起。

```
FRU LEDs status
```

```
=====
```

```
FRU LED ID 39 = SFM61 FAULT LED
```

```
FRU LED ID 39 is on
```