



CXone Mpower EXPERT

ディスク交換後、ディスクはメンテナンスプールイベントに移行します

https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/Disk_goes_into_maintenance_pool_ev...

Updated: Wed, 22 Apr 2026 08:47:59 GMT

環境

- ONTAP 9
- ディスク交換

問題

- 交換後もディスクのテストが再開されます。

例：

```
Fri Sep 03 14:57:28 -0500 [node01: config_thread:
raid.disk.maint.start:notice]: Disk 0c.10.2 Shelf 10 Bay 2 [NETAPP
X343_TA15E1T8A10 NA00] S/N [Y9T0A0WUF4UR] UID
[50000399:C8A02D54:00000000:00000000:00000000:00000000:00000000:00000000:0000
will be tested.
Wed Sep 08 08:20:44 -0500 [node01: config_thread:
raid.disk.maint.start:notice]: Disk 0c.10.2 Shelf 10 Bay 2 [NETAPP
X343_TA15E1T8A10 NA00] S/N [41M0A017F4UR] UID
```

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

