



CXone Mpower EXPERT

更换磁盘后、磁盘显示为故障

https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/Disk_is_shown_as_failed_after_replac...

Updated: Wed, 22 Apr 2026 07:33:04 GMT

适用场景

- Data ONTAP 8
- ONTAP 9
- 已更换故障磁盘

问题描述

新磁盘在“`sysconfig -a`”中显示为“`failed`”或“`failed—unsupported`”