



# CXone Mpower EXPERT

## 更换磁盘后，磁盘仍保留在损坏的池中

[https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/Disk\\_remains\\_in\\_broken\\_pool\\_after\\_di...](https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/Disk_remains_in_broken_pool_after_di...)

Updated: Wed, 22 Apr 2026 07:32:34 GMT

### 适用场景

- FAS8040
- ONTAP 9
- NS224

### 问题描述

- `sysconfig -a` 即使在更换磁盘后、故障磁盘信息仍会显示在输出中。

```
slot 0: SAS Host Adapter 0a (PMC-Sierra PM8001 rev. C, SAS, <UP>)
  Firmware rev:      01.12.09.00
  Base WWN:          5:00a098:XXXXXX:a0
  Phy State:         [0] Enabled, 6.0 Gb/s
                     [1] Enabled, 6.0 Gb/s
                     [2] Enabled, 6.0 Gb/s
```

```
[3] Enabled, 6.0 Gb/s
QSFP Vendor:      Amphenol
QSFP Part Number: 112-00178+A0
QSFP Type:        Passive Copper 5m ID:00
QSFP Serial Number: APF16XXXX444W
```

```
03.2: NETAPP X316_HAKPE06TA07 NA00 5614.6GB 520B / sect (AAAAAAAA) (Failed)
```

- 更换的磁盘同时显示在备用池和损坏的池中。

```
Pool0 spare disks
```

```
RAID Disk Device HA SHELF BAY CHAN Pool Type RPM Used (MB / blks) Phys (MB / blks)
```

```
-----
```

```
spare 3b.03.2 3b 3 2 SA: B 0 FSAS 7200 5614621/11498743808 5625872/11521787400
```

```
Broken disks
```

```
RAID Disk Device HA SHELF BAY CHAN Pool Type RPM Used (MB / blks) Phys (MB / blks)
```

```
-----
```

```
failed 0a.03.2 0a 3 2 SA: A 0 FSAS 7200 5614621/11498743808 5625872/11521787400
```