



CXone Mpower EXPERT

节点Shell中的磁盘名称重复、但集群Shell中的磁盘名称不重复

https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/Duplicate_disk_name_in_node_shell_...

Updated: Wed, 22 Apr 2026 08:47:55 GMT

适用场景

- ONTAP 9
- FAS8700
- DS460C磁盘架

问题描述

- 磁盘名称重复、但UUID、串行、路径等不同
- 集群Shell显示为正常、但节点Shell显示重复的磁盘名称和托架位置
- 无"disk.duplicate"错误
- sysconfig -a显示正确
- 从ONTAP 重新启动驱动器后、问题描述 未修复

```
Disk: 0b.20.37 Shelf: 20 Bay: 37 Sec Name: 0c.20.37 Path-Based Disk Name: NODE2:0c.20.37 NODE2:0b.20.37 NODE1:0b.20.37 NODE1:0c.20.37 ----- (Problem Drive) Disk: 0b.20.37 Shelf: 20 Bay: 37 Sec Name: 0c.20.37 Path-Based Disk Name: NODE2:0c.20.38 NODE2:0b.20.38 NODE1:0b.20.38
```

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

