



# CXone Mpower EXPERT

## 由于bootarg.storageencryption.support配置不当、“正在进入FM状态：5”

[https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/Entering\\_FM\\_state5\\_due\\_to\\_misconfig...](https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/Entering_FM_state5_due_to_misconfig...)

Updated: Wed, 22 Apr 2026 04:09:20 GMT

### 适用场景

- AFF 型号
- FAS 型号
- ONTAP 9
- FIPS 或 SED 驱动器

### 问题描述

- 在硬件维护之后，节点会报告以下内容：

```
[localhost:disk.encryptNoSupport:ALERT]: Detected FIPS-certified encrypting drive  
0n.4, but FIPS drives are not supported on this node. 48 of 48 disks checked are  
FIPS-certified.
```

或

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

Dec 01 14:34:15 [localhost:disk.encryptNoSupport:error]: Detected FIPS-certified encrypting disk 0b.00.3, but bootarg.storageencryption.support indicates that FIPS disks should not be present. 24 of 24 disks checked are FIPS disks.

- 节点在等待交还时仍会生成以下错误：

```
Waiting for giveback...(Press Ctrl-C to abort wait)Entering FM state:5 because
mbFound:0 local in headswap:0
Entering FM state:5 because mbFound:0 local in headswap:0
Entering FM state:5 because mbFound:0 local in headswap:0
Entering FM state:5 because mbFound:0 local in headswap:0
Entering FM state:5 because mbFound:0 local in headswap:0
```

- 集群报告以下内容：

```
Cluster1::> storage failover show
```

```
Takeover
```

```
Node           Partner           Possible State Description
```

```
-----
```

Cluster1-01	Cluster1-02	-	Kernel loaded
Cluster1-02	Cluster1-01	false	In takeover

```
2 entries were displayed.
```