



FAS70 新设置 PANIC : sk_cycles_per_msec 800000

https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/FAS70_new_setup_PANIC__%3A_sk_...

Updated: Wed, 22 Apr 2026 04:08:09 GMT

适用场景

FAS70

问题描述

新的设置节点将无法启动ONTAP或维护模式，出现以下紧急情况：

```
PANIC : sk_cycles_per_msec 800000: start 0, end 0, ontap_freq 800000155
```