



# CXone Mpower EXPERT

## 在高延迟系统操作期间、FCP wqe错误重复出现

[https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/FCP\\_WQE\\_error\\_repeats\\_during\\_high...](https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/FCP_WQE_error_repeats_during_high...)

Updated: Wed, 22 Apr 2026 07:31:45 GMT

### 适用场景

- ONTAP 9.x
- Emulex LPe32000 FCP目标端口

### 问题描述

`scsitarget.slifct.wqeError` 在高延迟系统操作期间，`fcp.io.status` 会从**Emulex FCP目标端口(Emulex LPe32000 (LPe32002) rev 12)**重复。

### 示例：

```
7/23/2021 04:05:48 FAS-01 DEBUG scsitarget.slifct.wqeError: FC port 10a has a
WQE processing failure of type SLI_IO_ABORT, command N/A, subtype x0, with
status of 3 and an extended status x5 for NPIV port 3.
```

```
7/23/2021 04:05:48 FAS-01 DEBUG fcp.io.status: STIO Adapter:10a IO WQE
```

failure, Handle 0x6, S\_ID: C70160, OX\_ID: F56, Status 0x3 Ext\_Status 0x5

7/23/2021 04:05:49 FAS-01 ERROR **waf1.cp.toolong**: Aggregate aggr1 experienced a long CP.