



CXone Mpower EXPERT

在 CPU0 消息上调用 CPU_reset 后重新启动

https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/Reboot_after_cpu_reset_called_on_cp...

Updated: Wed, 22 Apr 2026 07:28:44 GMT

适用场景

FAS2520

问题描述

- 启动环路中的节点。
- 控制台日志，包含最新消息，例如：

```
...  
cryptomod_fips: Crypto FIPS self-test: 'Self-integrity' passed.  
Starting nvmmf-tgt module...  
Waiting for D-blade to resume boot  
boot state: pre-disk  
cpu_reset called on cpu#0
```

- 诊断（SLDiags）中未报告任何问题。
- 更换控制器后，问题描述 仍会保留。

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information