



无法更新单磁盘架IOM12B模块固件

https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/Single_shelf_IOM12B_module_firmwar...

Updated: Wed, 22 Apr 2026 07:31:44 GMT

适用场景

DS224C

问题描述

- 无法从SYSCONFIG-A 更新单磁盘架IOM12B模块固件：

```
Shelf 53: DS224-12  Firmware rev.  IOM12B A: 0202  IOM12B B: 0141
```

- EMS-LOG-FILE.GZ 报告了错误：

```
Wed May 07 15:53:57 +0900 [node_name: dsa_sfu: sfu.firmwareDownrev:error]: Disk shelf firmware needs to be updated on 1 disk shelf.
```

```
Wed May 07 16:03:22 +0900 [node_name: dsa_disc: ses.mismatch.fw.version:error]: The disk shelf modules on disk shelf 11b.53 are running two different firmware versions. Disk shelf module A is running 0202, and disk shelf module B is running 0141.
```

Wed May 07 16:03:22 +0900 [node_name: dsa_disc:
sfu.firmwareDownrev.shelf:error]: Shelf 11b.shelf53 has downrev firmware.