



SP/BMC固件升级挂起

https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/SP_BMC_firmware_upgrade_is_hung

Updated: Wed, 22 Apr 2026 07:28:55 GMT

适用场景

- 服务处理器 (SP)
- 底板管理控制器 (BMC)
- ONTAP 9

问题描述

执行SP/BMC固件升级时、没有错误。但是、升级会挂起并在几分钟后停止。

```
cluster1::*>system service-processor image update-progress show
```

Node	In Progress	Start Time	Percent Done	End Time
node01	no	10/1/2021 12:49:28	0	10/1/2021 12:49:50
node02	no	10/22/2021 07:54:47	0	10/22/2021 07:57:32

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

2 entries were displayed.