



CXone Mpower EXPERT

SP 心跳 LED 亮起，未检测到故障

https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/SP_heart_beat_LED_on_with_no_failu...

Updated: Wed, 22 Apr 2026 11:39:18 GMT

适用场景

- FAS8200

问题描述

- system led show all 显示 SP heart beat LED 的是：

```
SP01-01*> system led show all
FRU LED ID 1 is off
FRU LED ID 2 is off
FRU LED ID 3 is off
FRU LED ID 4 is on
FRU LED ID 5 is off
...
FRU LED ID 28 is off
```

```
SP01-01*> system led show
```

Display status of the specified <FRU-LED-ID>.

```
<FRU-LED-ID>:
```

- 1 - SP Controller Fault LED
- 2 - SP Chassis Locate LED
- 3 - SP System Fault LED
- 4 - SP Heartbeat LED
- 5 - SP Fan 1 Fault LED
- ...
- 28 - SP RTC Battery Fault LED (Coin Cell Battery)
- all others are not valid

- `service-event show` 在不从 `sp` 提示符和 `ONTAP` 提示符检测到故障的情况下：

```
SP01-01*>system service-event show
```

ID	FRU Description	Fault Reason
----	-----------------	--------------

```
-----  
-----
```

Fault Lights On:

```
cluster::> system controller service-event show -instance
```

There are no entries matching your query.