



SP在固件更新期间重试下载环路

https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/SP_Retry_Downloading_loop_during_f...

Updated: Wed, 22 Apr 2026 07:34:25 GMT

适用场景

- FAS/AFF
- ONTAP 9

问题描述

在SP固件升级期间、将停留在重试下载循环中

```
BMC node-01*> bmc update http://10.10.10.10:8080/SP\_FW.tar.gz -f
Downloading package...
Uncompressing package... (md5sum=61b41b6f981c25f213c3ccfe260c583c)
Retry Downloading...
Downloading package...
Uncompressing package... (md5sum=61b41b6f981c25f213c3ccfe260c583c) ^C
Retry Downloading...
Downloading package...
Uncompressing package... (md5sum=61b41b6f981c25f213c3ccfe260c583c)
```

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

Retry Downloading...
Downloading package...^C
BMC Firmware Update interrupted. Exiting.