



系统运行状况警报报告 AllPathToOneEndOfStack_Alert

https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/System_health_alert_reports_AllPathT...

Updated: Wed, 22 Apr 2026 04:08:28 GMT

适用场景

- ONTAP 9
- FAS8300

问题描述

system health alert show 报告 AllPathToOneEndOfStack_Alert

示例：

```
Monitor    node-connect
Alert ID   AllPathToOneEndOfStack_Alert
Alerting Resource  1
Subsystem  SAS-connect
Indication Time   Wed Nov 17 13:29:18 2021
```

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

Perceived Severity Major
AutoSupport Triggered true
Probable Cause Cable_tamper
Corrective Actions 1. Consult the guide applicable to your IOM12 disk shelf to review cabling rules and complete the SAS cabling worksheet for your system.
2. Connect controller CNSENAS07-01 to the first and last disk shelves of stack 1.
3. Verify that controller CNSENAS07-01 is cabled to IOM A and IOM B of stack 1.
4. Contact technical support if the alert persists.
Node ID Node1
Enable Asup for This Alert true
Alert Clear Time