



ifgrp中的网络端口已关闭

https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/The_network_port_is_down_in_the_ifgrp

Updated: Wed, 22 Apr 2026 09:13:39 GMT

适用场景

- ONTAP 9
- AF/FAS系统

问题描述

- NIC端口已关闭

```
slot 1: Dual 10 Gigabit Ethernet Controller IX1-SFP+
  e1a MAC Address:  f8:f2:1e:2d:0d:b4 (auto-unknown-fd-down)
    SFP Vendor:      Intel Corp
    SFP Part Number: AFBR-709DMZ-IN3
    SFP Serial Number: AD181630GTX
  e1b MAC Address:  f8:f2:1e:2d:0d:b5 (auto-10g_sr-fd-up)
    SFP Vendor:      Intel Corp
    SFP Part Number: AFBR-709DMZ-IN3
    SFP Serial Number: AA180930D1D
```

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

- IFCONFIG -VVVM 在中、ASUP 显示 SFP 的 TX 功率较低

```
e1a: flags=8843<UP,BROADCAST,RUNNING,SIMPLEX,MULTICAST> metric 0 mtu 1500
  options=6c07bb<RXCSUM, TXCSUM, VLAN_MTU, VLAN_HWTAGGING, JUMBO_MTU, VLAN_HWCSUM, TSO4, TSO
  ether f8:f2:1e:2d:0d:b4
  media: Ethernet autoselect (autoselect <full-duplex, rxpause, txpause>)
  status: no carrier
  plugged: SFP/SFP+/SFP28 10G Base-SR (LC)
  vendor: Intel Corp PN: AFBR-709DMZ-IN3 SN: AD181630GTX DATE: 2018-04-23
  module temperature: 28.73 C Voltage: 3.33 Volts
  RX: 0.53 mW (-2.70 dBm) TX: 0.00 mW (-40.00 dBm)
```