



CXone Mpower EXPERT

无法获取一个节点的电源状态

https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/Unable_to_get_power_status_of_one_...

Updated: Wed, 22 Apr 2026 05:16:35 GMT

适用场景

- ONTAP 9
- AFF A70

问题描述

- 无法获取一个AFF A70节点的电源状态
- `Command system node power show` 报告

```
Cluster::*> system node power show
```

```
Node          Status
```

```
-----  
Node-01 on
```

```
Error: Failed to initiate power control operation due to API error
```

```
Node-02 -
```

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information