



---

## SolidFire 节点上的 bmcSelectError

[https://kb-cn-stage.netapp.com/on-prem/SolidFire/Element\\_OS\\_Kbs/bmcSelEccError\\_on\\_SolidFire\\_Node](https://kb-cn-stage.netapp.com/on-prem/SolidFire/Element_OS_Kbs/bmcSelEccError_on_SolidFire_Node)

Updated: Wed, 22 Apr 2026 03:54:00 GMT

### 适用场景

- NetApp N5000 系列
- NetApp Element 软件
- 智能平台管理接口 ( IPMI )

### 问题描述

NetApp Element 软件会记录以下错误，并可在 NetApp Active IQ 中观察到：

```
bmcSelEccError - Uncorrectable Machine Check Exception detected in SEL Log. Please contact support.
```

---

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information