



节点上出现间歇性主服务和Element身份验证警报

https://kb-cn-stage.netapp.com/on-prem/SolidFire/Element_OS_Kbs/Intermittent_Master_Service_and_...

Updated: Wed, 22 Apr 2026 07:30:34 GMT

适用场景

NetApp H 系列

问题描述

- 警报是间歇性的、但可以自行解决
- NetApp SolidFire Active IQ :
 - 错误代码： `unresponsiveService`
 - 详细信息: `A master service is not responding.`
 - 错误代码： `authenticationServiceFault`
 - 详细信息: `Element Auth container has been in the NotReady state for too long on node <#.. Please contact support if this problem persists.`

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information