



# CXone Mpower EXPERT

## 重复的cf.hwAssist错误

[https://kb-cn-stage.netapp.com/on-prem/ontap/Ontap\\_OS/OS-KBs/Repeated\\_cf.hwassist\\_errors](https://kb-cn-stage.netapp.com/on-prem/ontap/Ontap_OS/OS-KBs/Repeated_cf.hwassist_errors)

Updated: Wed, 22 Apr 2026 04:07:44 GMT

### 适用场景

- 产品型号
  - FAS22xx、FAS255x、FAS26xx、FAS32xx、FAS62xx、FAS80xx、FAS82xx、FAS9xxx
  - AF-A200、AF-A300、AF-A700
- 操作系统
  - 8.0 到 8.2.5 (含)之间的ONTAP 7-模式
  - 集群模式ONTAP 介于 8.2 和 9.1P2之间 (包括8.2和9.1P2)

### 问题描述

`cf.hwassist.missedKeepAlive` 在新平台部署上重复出现以下错误：

[nodeA : cf\_hwassist : cf.hwassist.missedKeepAlive : error] : hw\_assist:未收到配对节点发出的保活警报(NodeB)。

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

