



升级ONTAP 失败、一个节点启动失败

https://kb-cn-stage.netapp.com/on-prem/ontap/Ontap_OS/OS-KBs/Upgrade_ONTAP_failed_with_one_...

Updated: Wed, 22 Apr 2026 04:08:11 GMT

适用场景

- FAS8200
- ONTAP 9

问题描述

- 将ONTAP从9.3P6升级到9.5P19。
- 升级ONTAP后、一个节点Node02启动失败。

```
::> storage failover show
```

Node	Partner	Takeover Possibel	State Description
node01	node02	false	Connected to node02,partial giveback,takeover

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

is not possible: The

version of software running on each node of the SFO pair
is

incompatible, NVRAM log not synchronized.

node02 node01 - Waiting for Cluster application to come online
on the local node

offline application: mgmt,vldb,vifmgr,bcomd,crs.

- node01处于活动状态并运行ONTAP 9.3
- 通过SSH连接到node02 系统控制台，node02运行ONTAP 9.5，但许多服务未启动。
- `::> cluster ring show` 在这两个节点中找不到配对节点 `system console`。