



CXone Mpower EXPERT

如何对主机冗余丢失警报进行故障排除

https://kb-cn-stage.netapp.com/on-prem/E-series/SANtricity-OS-Kbs/How_to_troubleshoot_Host_Redun...

Updated: Wed, 22 Apr 2026 14:49:25 GMT

状态信息

适用场景

NetApp E 系列

问题描述

- Recovery Guru和主要事件日志(MEL)报告以下错误：
 - `Loss of host-side connection redundancy detected`
 - `Volume not on preferred path due to AVT/RDAC failover`
- 主机冗余丢失表示主机只有一个控制器的路径。出现这种情况的主要原因有两个：
 1. 此主机仅设置了与一个控制器的连接。
 2. 主机丢失网络结构中的一条路径、从而导致指向一个控制器的路径出现故障。这可能是以下任一原因造成的。
 - 环境发生变化、例如布线发生变化。
 - SAN错误发生原因故障路径。

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information