



对Cisco集群交换机执行show install all Impact kickstart命令失败

https://kb-cn-stage.netapp.com/on-prem/Switches/Cisco-KBs/show_install_all_impact_kickstart_comma...

Updated: Wed, 22 Apr 2026 07:32:28 GMT

适用场景

Cisco集群交换机

问题描述

验证下载到交换机的映像失败

```
show install all impact kickstart n5000-uk9-kickstart.7.3.7.N1.1b.bin system
n5000-uk9.7.3.7.N1.1b.bin
```

```
Verifying image bootflash:/n5000-uk9-kickstart.7.3.7.N1.1b.bin for boot variable
"kickstart".
```

```
[#           ] 0%[#####] 100% -- SUCCESS
```

```
Verifying image bootflash:/n5000-uk9.7.3.7.N1.1b.bin for boot variable "system".
```

```
[#           ] 0%[#           ] 0% -- FAIL. Return code
0x4045001F (image MD5 checksum error).
```

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

Install has failed. Image verification failed (0x40930011)

```
=====  
Error Id: 0x4045001F  
Error Facility: bootvar  
Error Description: image MD5 checksum error
```

Image MD5 checksum error can happen due to one of the following reason(s):
[1] The target image is possibly corrupt. Copy the target image again and try the "install all" command