



Brocade FirmwareCommit 失败错误

https://kb-cn-stage.netapp.com/on-prem/Switches/Brocade-KBs/Brocade_firmwarecommit_failed_error

Updated: Wed, 22 Apr 2026 03:54:00 GMT

适用场景

Brocade 交换机上的端口

问题描述

固件升级失败，出现错误 `firmwarecommit failed`