



NiCE

Brocade端口被卡为G端口

https://kb-cn-stage.netapp.com/on-prem/Switches/Brocade-KBs/Brocade_port_is_stuck_as_G_port

Updated: Wed, 10 Jun 2026 19:11:58 GMT

适用场景

- Broadcom 交换机
- Brocade G610

问题描述

- 无法将Brocade端口配置为E POT、因为它已停留为G端口
- 更换SFP和缆线未解决问题
- hareboot 没有帮助

示例：

```
Index Port Address Media Speed State Proto
=====
1 1 6f0100 id N32 Online FC G-Port
```

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information