



Brocade 交换机固件升级过程挂起

https://kb-cn-stage.netapp.com/on-prem/Switches/Brocade-KBs/Brocade_switch_firmware_upgrade_pr...

Updated: Wed, 22 Apr 2026 10:04:58 GMT

适用场景

DCX-8510 Brocade SAN交换机

问题描述

'firmwaredownload -s' 使用命令时、从7.3.1 B升级到7.4.2 C的交换机固件将挂起。以下命令显示新映像已下载到活动CP上。

```
root> firmwareShow
Slot Name Appl Primary/Secondary Versions Status
-----
4 CP0 FOS v7.3.1b ACTIVE
      * v7.4.2c
5 CP1 FOS v7.3.1b STANDBY
      v7.3.1b
```

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

* Local CP

WARNING: Firmwaredownload is in progress.

root>