



---

## 由于流量隔离(TI)分区、Brocade交换机升级失败

[https://kb-cn-stage.netapp.com/on-prem/Switches/Brocade-KBs/Brocade\\_switch\\_upgrade\\_fails\\_due\\_to...](https://kb-cn-stage.netapp.com/on-prem/Switches/Brocade-KBs/Brocade_switch_upgrade_fails_due_to...)

Updated: Fri, 24 Apr 2026 12:18:35 GMT

### 适用场景

Brocade 交换机上的端口

### 问题描述

Brocade交换机固件从FOS v8.x.x.X升级到V9.x.X失败、并显示以下错误：

```
ERROR: Traffic Isolation (TI) Zones are detected on the switch and are no longer supported in the target version of fabric OS. (FID 31).
```