



## WWPN 未登录到 Brocade 交换机

[https://kb-cn-stage.netapp.com/on-prem/Switches/Brocade-KBs/WWPN\\_not\\_getting\\_logged\\_in\\_to\\_bro...](https://kb-cn-stage.netapp.com/on-prem/Switches/Brocade-KBs/WWPN_not_getting_logged_in_to_bro...)

Updated: Wed, 22 Apr 2026 10:27:36 GMT

### 适用场景

Brocade 交换机 G720

### 问题描述

- 将缆线插入 Brocade 交换机且端口进入 In\_Sync 状态后、未检测到 WWPN

```
Index Port Address Media Speed State Proto
=====
 35 35 01xx00 id N32 In_Sync FC
```

```
=====
```

```
Port 35:
```

```
=====
```

```
Identifier: 3 SFP
```

```
Connector: 7 LC
```

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

```

Transceiver: 6804406000000000 8,16,32_Gbps M5 sw Inter,Short_dist
.....
Vendor Name: BROCADE
Vendor OUI: 00:05:1e
Vendor PN: 57-1000333-01
...
Temperature: 59 Centigrade
Current: 0.000 mAmps
Voltage: 3291.7 mVolts
RX Power: -2.9 dBm (507.2uW)
TX Power: -1.5 dBm (715.4 uW)

```

- SFP的Rx和Tx处于最佳范围
- 将缆线移至其他可用端口后、WWPN仍不会登录
- 已更换交换机端口上连接到主机的缆线、WWPN仍未登录
- Link fail, loss sync 在展览上报告了一些错误，似乎是历史性的

```

/fabos/cliexec/porterrshow:
      frames  enc  crc  crc  too  too  bad  enc  disc  link  loss
loss  frjt  fbsy  c3timeout  pcs  uncor
      tx  rx  in  err  g_eof  shrt  long  eof  out  c3  fail  sync
sig
32:  4.2g  4.2g  0  0  0  0  0  0  2  35.7k  17.9k  411
    0  0  0  0  0  16.6k
33:  2.9g  668.2m  0  0  0  0  0  0  1  35.5k  17.9k  119
    0  0  0  0  0  9.4k

```

```

2023/07/20-23:34:32, [PORT-1003], 61891, FID 128, WARNING, G620B, Port 33
Faulted because of many Link Failures.
2023/07/20-23:37:54, [PORT-1003], 61897, FID 128, WARNING, G620B, Port 33
Faulted because of many Link Failures.
2023/07/20-23:41:16, [PORT-1003], 61903, FID 128, WARNING, G620B, Port 33
Faulted because of many Link Failures.
2023/07/20-23:44:43, [PORT-1003], 61909, FID 128, WARNING, G620B, Port 33
Faulted because of many Link Failures.

```

- 将同一条缆线移至不同交换机后、WWPN将登录