



SFP接收功率不是最佳

https://kb-cn-stage.netapp.com/on-prem/Switches/General_Kbs/SFP_receive_power_is_not_optimal

Updated: Wed, 22 Apr 2026 08:25:15 GMT

适用场景

- ONTAP
- 小型可插拔 (SFP)

问题描述

ONTAP通知风险：

Risk: **SFP receive power is not optimal**. Potential Impact: The host may encounter disruption while trying to reach the storage on the impacted port and can potentially lead to an outage. Details: SFP receive power of the SFP connected to port 2a is below the recommended value.