



CONTAPEXT-718 : ATto 7500N/7600N光纤网桥可能会意外重新启动

<https://kb-cn-stage.netapp.com/on-prem/ontap/MC/MC-Issues/CONTAPEXT-618>

Updated: Wed, 22 Apr 2026 08:25:36 GMT

问题描述

ATTO7600N接收[INFO Reset。硬件代码：L4监护程序0 warm (L4监护程序0热)]、然后重新启动