



CFDISK-1371: 适用于 S1653 型驱动器的 NA51 FW 版本

<https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-Issues/CFDISK-1371>

Updated: Wed, 22 Apr 2026 07:31:12 GMT

问题描述

具有 S1653 型号 ID 的驱动器的 NA51 驱动器固件版本包括更改，以帮助防止在低工作负载功耗情况下发生驱动器故障。此更改会影响由 3/31/00 检查条件确定的驱动器故障。

受影响驱动器的部件号和标识

ONTAP

Part Number	Model ID	Capacity	Update	FW	To
-------------	----------	----------	--------	----	----

X371	X371_S1653960ATE	960GB	NA51		
X374	X374_S1653960ATE	960GB	NA51		
X379	X379_S1653960ATE	960GB	NA51		
X382	X382_S1653960ATE	960 GB	NA51		
X357	X357_S16533T8ATE	3.8 TB	NA51		
X364	X364_S16533T8ATE	3.8 TB	NA51		
X319	X319_S16537T6ATE	7.6 TB	NA51		
X670	X670_S165315TATE	15 TB	NA51		

NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

X359 X359_S165330TATE 30 TB NA51