



CHW-1995 : FAS8300 闪存缓存 PCI 崩溃，出现 SKL_IIO 错误

<https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-Issues/CHW-1995>

Updated: Wed, 22 Apr 2026 08:47:49 GMT

问题描述

发生节点崩溃，并出现以下崩溃字符串，并且不影响主板的更换。

```
PANIC : Uncorrectable Machine Check Error at CPU14. SKL_IIO Error:  
STATUS<0xbb8000000000e0b> (VALID, UC, EN, MISCV, PCC, S, AR, CORR_ERR_STATUS (0), CORR_ERR_CNT (0), MS  
Machine Check from  
device(s) :RPT (128,0,0) :ErrSrcID(CorrSrc(0x8100),UCorrSrc(0x8250)), PLX PCIE 8733  
switch on Controller, Br[8733] (130,10,0): Link down.
```