



CONTAP-119131 : SNMP故障发生时交换机风扇和电源误报警

<https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-Issues/CONTAP-119131>

Updated: Wed, 22 Apr 2026 08:25:43 GMT

问题描述

- 交换机运行状况监视器警报 `SwitchFanNotPresent_Alert`、`SwitchPowerNotPresent_Alert` 和 `SwitchPowerUnknown_Alert` 被反复引发和清除。
- 必须引发所有三个警报才能应用此问题
- 影响以下交换机型号：

- BES-53248
- N3K-C3232C
- N9K-C9336C-FX2
- N9K-C92300YC
- MSN2100-CB2FC、MSN2100-CB2RC
- X190006-PE、X190006-PI

- 事件日志报告多个警报，例如：

```
hm.alert.raised: Alert Id = SwitchPowerUnknown_Alert , Alerting Resource =  
Switch1(Serial)/PowerSupply-1 raised by monitor ethernet-switch
```

```
hm.alert.raised: Alert Id = SwitchPowerNotPresent_Alert , Alerting Resource =  
Switch1(Serial)/PowerSupply-1 raised by monitor ethernet-switch
```

```
hm.alert.raised: Alert Id = SwitchFanNotPresent_Alert , Alerting Resource =  
Switch1(Serial)/Fan Module-1 raised by monitor ethernet-switch
```

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

- "system health alert show" 命令输出也显示这些警报