



CONTAP-243154 : "SwitchFanNotPresent_Alert"在将 ONTAP 升级到 9.13.1 及更高版本后由 CSHM 针对集群网络交换机报告

<https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-Issues/CONTAP-243154>

Updated: Wed, 22 Apr 2026 08:25:14 GMT

问题描述

- 系统报告类似于以下内容的警报：

```
[Node02: cshmd: hm.alert.raised:alert]: Alert Id = SwitchFanNotPresent_Alert ,  
Alerting Resource = switchA(xxxxxx)/Fan Module-1 raised by monitor ethernet-switch  
[Node02: cshmd: hm.alert.raised:alert]: Alert Id = SwitchFanNotPresent_Alert ,  
Alerting Resource = switchA(xxxxxx)/Fan Module-2 raised by monitor ethernet-switch  
[Node02: cshmd: hm.alert.raised:alert]: Alert Id = SwitchFanNotPresent_Alert ,  
Alerting Resource = switchA(xxxxxx)/Fan Module-3 raised by monitor ethernet-switch  
[Node02: cshmd: hm.alert.raised:alert]: Alert Id = SwitchFanNotPresent_Alert ,  
Alerting Resource = switchA(xxxxxx)/Fan Module-4 raised by monitor ethernet-switch  
[Node02: cshmd: hm.alert.raised:alert]: Alert Id = SwitchFanNotPresent_Alert ,  
Alerting Resource = switchA(xxxxxxxx)/Fan Module-1 raised by monitor ethernet-switch
```

- 但是，交换机信息并不表明交换机硬件组件存在任何问题。