



CONTAP-303498: ONTAP 集群节点意外重启

<https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-Issues/CONTAP-303498>

Updated: Wed, 22 Apr 2026 11:21:22 GMT

问题描述

- 在更换配对节点 PCM 并执行存储故障转移交还后，ONTAP 集群节点意外重新启动，并显示以下消息：

```
aggr aggr1_node1: raid volfsm, fatal multi-disk error..  
Raid type - raid_dp  
Group name plex0/rg0 state NORMAL. 4 disks failed in the group.  
Disk 0a.00.1P1 Shelf 0 Bay 1 [NETAPP X357_SLNGE3T8ATE NA54] S/N  
[XXXXXXXXXXXXXXXX] UID error: disk does not exist.  
Disk 0a.00.2P1 Shelf 0 Bay 2 [NETAPP X357_SLNGE3T8ATE NA54] S/N  
[XXXXXXXXXXXXXXXX] UID error: disk does not exist.  
Disk 0a.00.3P1 Shelf 0 Bay 3 [NETAPP X357_SLNGE3T8ATE NA54] S/N  
[XXXXXXXXXXXXXXXX] UID error: disk does not exist.  
Disk /aggr1_node1/plex0/rg0/0a.00.4P1 Shelf 0 Bay 4 [NETAPP  
X357_SLNGE3T8ATE NA54] S/N [XXXXXXXXXXXXXXXX] UID  
version: 9.8P3: Sat Mar 27 04:59:49 EDT 2021
```