



## CONAP-360430 : 针对NVMEM.battery.chgrFailed发出的警报不正确

<https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-Issues/CONTAP-360430>

Updated: Wed, 22 Apr 2026 08:24:20 GMT

### 问题描述

在以下特定情况下、ONTAP可能会针对nvmem.battery.chgrFailed事件发出错误警报：

1. NVDIMM电池处于学习周期时错误触发。
2. 如果NVDIMM电池充电器完全不工作、则无法触发。
3. 如果NVDIMM电池充电器正在 充电且NVDIMM电池正在 放电 五分钟、则系统将在20分钟后关闭、而不是触发该事件。

仅适用于以下确切的ONTAP版本：

- 9.16.1
- 9.16.1RC1
- 9.15.1P7
- 9.15.1P6
- 9.15.1P5
- 9.14.1P11
- 9.14.1P10
- 9.13.1P13
- 9.12.1P16
- 9.10.1P20

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information